

REPLACEMENT FOR

PUP 720
'79~'83



REPLACEMENT FOR

PUP 720
'84-'85



FRONT BUMPER
901.NS40025A
OE:62023 -10W01



CORNER LAMP
938.NS1103 **215-1506-2**
R 26160-11W000 L 26165-11W000



CORNER LAMP
938.NS1151K **215-1504-2**
R 26160-08W01 L 26165-08W01



CORNER LAMP
938.NS1103C **215-1506-3**
R 26160-11W000 L 26165-11W000




CORNER LAMP
938.NS1151 **215-1504-1**
R 26160-50W10 L 26165-50W10



FRONT LAMP
932.NS1159 **315-1601**
R 26120-04W00 L 26125-04W00



TAIL LAMP
931.NS1322B **215-1919-2**
R 26550-08W05 L 26556-08W05



FRONT LAMP
932.NS1160 **215-1605-0**
R 26120-02W00 L 26125-02W00



TAIL LAMP
931.NS1322C **215-1919-1**
R 26550-08W00 L 26556-08W00

All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

NS

email:market@daiwa-motor.com