

REPLACEMENT FOR

TEANA / ALTIMA '19~



FRONT BUMPER
901.NS08051BA
OE:62022-6CT0A



WATER TANK UPPER COVER
911.NS44286A
OE:21559-6CT0D



HEAD LAMP
930.NS7140
R:



REAR BUMPER
901.NS08052BA
OE:85022-6CT0A




FOG LAMP COVER
913.NS2146A
R:62256-6CT1A L:62257-6CT1A



DAYTIME RUNNING LAMP
939.NS7087
R:26130-6CT0A L:26135-6CT0A



FRONT BUMPER REINFORCEMENT
911.NS44287A
OE:62091-6CT0A




FAN SHROUD
512.NS2019
OE:62500-6CT0A



FOG LAMP
939.NS7088
R:26150-8992D L:26155-8992D




FRONT BUMPER BRACKET
911.NS44288A
R:62220-6CT0A L:62221-6CT0A



FRONT TRAILER COVER
901C.NS11007
OE:622A0-6CT0A



GRILLE
900.NS27316GA
OE:62310-6CT0A



REAR BUMPER BRACKET
911.NS44289A
R:85220-6CT0A L:85221-6CT0A



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

NS

email:market@daiwa-motor.com