

REPLACEMENT FOR


SYLPHY '06



REAR BUMPER LAMP
932.NS7315
OE:26580-EW800



INNER FENDER
915.NS11157A
R:63842-EW800 L:63843-EW800



HOOD MOULDING
923.NS07203A
OE:65834-EW800




HEAD LAMP
930.NS7119E
R:26015-EW80A L:26065-EW80A



DOOR MIRROR ELECTRIC
980.NS741
R:96301-EW80A L:96302-EW80A



COVER, ENGINE UNDER
957.NS22023A
OE:75892-ED500



TRUNK LID MOULDING
923.NS2026A
OE:84921-EW800



TAIL LAMP
931.NS7608
R:26550-EW010 L:26550-EW010



GRILLE
900.NS27255GA
OE:62310-EW800



COVER, ENGINE UNDER
957.NS22024A
OE:75898-EW000



FOG LAMP COVER
913.NS1208
R:62257-EW810 L:62256-EW810



BACK LAMP
933.NS1310
R:




FRONT BUMPER
901.NS08010BA
OE:62022-EW840



AIR DEFLECTOR - RADIATOR
911.NS44299A
R:62822-EW800 L:62823-EW800



FOG LAMP COVER
913.NS1209
R:



REAR BUMPER LAMP
932.NS7314
R:26560-EW00A L:26565-EW00A



REAR BUMPER
901.NS08011BA
OE:85022-EW840



RADIATOR TOP COVER
911.NS44298A
OE:62322-EW800



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

NS

email:market@daiwa-motor.com