

REPLACEMENT FOR

6 '08~



TAIL LAMP
931.MZ1973
R:GS1F51180E L:GS1F51170E



FRONT BUMPER
901.MZ07102BA
OE:



REAR BUMPER SUPPORT
911.MZ44103
OE:



HEAD LAMP ELECTRIC
930.MZ1155E 216-1155
R:GS1F510KOE L:GS1F510KOE



TAIL LAMP
931.MZ7974 216-1973-C
R:GS1F51150G L:GS1F51160G



REAR BUMPER
901.MZ07103BA
OE:



FOG LAMP COVER
913.MZ9375
OE:



FOG LAMP
939.MZ2021 216-2021
R:GS1D51680B L:GS1D51690B



REAR BUMPER REFLECTOR
932.MZ7001
OE:



BUMPER GRILLE
901G.MZ04906BA
OE:



INNER FENDER
915.MZ11120
OE:



BACK LAMP RH
933.MZ1308R
OE:GS1F513F0E



3RD BRAKE LAMP
940.MZ6113
OE:



RADIATOR SUPPORT
904.MZ30105A
OE:



HEAD LAMP BRACKET
930.MZ6662
OE:



BACK LAMP LH
933.MZ1308L
OE:GS1D513G0H



GRILLE
900.MZ08001GA
OE:



FRONT BUMPER SUPPORT
911.MZ44102
OE:



SIDE SKIRT
908.MZ52003
OE:

All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

MZ

email:market@daiwa-motor.com