

REPLACEMENT FOR

TEANA 06~



FRONT BUMPER
901.NS04994BA
OE:85022-9W80H



REAR MUDGUARD
922.NS6004Z
OE:



FRONT BUMPER
901.NS04995BA
OE:85022-9W80H



INNER FENDER
915.NS11096
R:63844-7W50A L:63843-7W50A




HEAD LAMP
930.NS7665
L:26060-7W51A-B019



GRILLE
900.NS27294GA
OE:62310-EW800



FOG LAMP
939.NS7001
R 26150-7W50A L 26155-7W50A



BUMPER INNER ABSORBER
911.NS44224A
OE:



TAIL LAMP
931.NS0001
R 26550-7W50A L 26555-7W51A



FRONT MUDGUARD
922.NS6003Z
OE:F38E-09W80A



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

NS

email:market@daiwa-motor.com