

REPLACEMENT FOR

CX.5 '17



BACK LAMP
933.MZ5429
R:KB88-51-3F0 L:KB88-51-3G0



GRILLE UPPER BOARD
911.MZ44120A
OE:KD5A-50-033



FENDER TRIM FRONT
943.MZ1203
R:KD5H-51-W30 L:KD5H-51-W20



HEAD LAMP
930.MZ7005
R:



GRILLE
900.MZ08013GA
OE:KD5A-50-710



GRILLE BRACKET
911.MZ44121
R:KD5H-50-151 L:KD5H-50-161



FENDER TRIM REAR
943.MZ12004
R:KD5H-51-W60 L:KD5H-51-W50



HEAD LAMP
930.MZ7006
R:



FRONT BUMPER
901.MZ07112BA
OE:KD13-50-031



FOG LAMP COVER
913.MZ9389
R:KD5H-50-C11 KIKD5H-50-C21




BODY MOULDING
923.MZ3007
OE:




REAR BUMPER LAMP
932.MZ7009
R:



REAR BUMPER
901.MZ07113BA
OE:KD5H-50-221



GRILLE MOULDING
923.MZ3006A
R:KD5H-50-7J1 L:KD5H-50-7K1



TAIL LAMP
931.MZ7014
R:K123-51-150 L:K123-51-160



TOP COVER, WATER TANK
911.MZ44118A
OE:KD5A-50-717



SIDE SKIRT
908.MZ52005
R:KD5H-51-940 L:KD5H-51-950



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

MZ

email:market@daiwa-motor.com